

S500 Ethernet – G1927

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.03	CN1374	Occasional power up problem corrected
1.02	CN1346	No change to product. Change to order of test procedure to speed up testing.
1.01	CN1336	Change to give extra protection in the event of the RTU being forced awake with a flat battery.
1.00	----- -	Released to production.