

S1000 PSU – J/G1401

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
2.00	CN753	Glue replaced by tie-wrap to hold T6 component mechanically.

S1000 MKII CPU – J/G1434

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
4.04	CN1024	Add battery information to product.
4.3	CN908	Test procedure (sleep current parameter) changed.
4.2	CN781	Dimension error on pcb.

S1000 Multi-media Modem – J/G1403

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
2.21	CN1063	BABT approvals change to self certification.BABT labels removed.

S1000 V22bis Modem – J/G1405

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
2.03	CN1064	BABT approvals change to self certification.BABT labels removed.

S1000 V21, V23 FFSK Modem – J/G1406

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.10	CN1065	BABT approvals change to self certification.BABT labels removed.

S1000 Digital Input – J/G1410

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
2.00	CN774	Original capacitor type/value(s) reinstated due to previous sourcing problems.

S1000 Digital Output – J/G1411

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.7	CN933	Capacitor added to remove noise problem found during test of this batch only. (Customer not affected).

S1000 Analogue Input – J/G1416

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.03	CN1100	Calibration pot changed (all AI boards).
1.2	CN796	Component changes (no affect to customer).

S1000 Analogue Input Expansion – J/G1417

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.03	CN1100	Calibration pot changed (all AI boards).
1.2	CN796	Component changes (no affect to customer).

S1000 Analogue Ouput – J/G1413

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
2.6	CN1018	Two capacitors per channel changed to high temperature variants

S1000 CIP Scanner – J/G1418

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.2	CN633	Changes to parts list/test procedure to correct errors.

S1000 CIP Scanner Daughter Board – J/G1426

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.2	CN633	Changes to parts list/test procedure to correct errors.

S1000 Mixed IO – J/G1419

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.5	CN673	Errors in parts lists corrected.

S1000 Mixed IO Daughter Board – J/G1427

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.5	CN673	Errors in parts lists corrected.

S1000 VFC Matrix Input – J/G1428

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
-----------------	---------------	------------------------------

2.0	CN804	Dimension error on pcb.
-----	-------	-------------------------

S1000 Multiplexed Digital Input – J/G1420

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
-----------------	---------------	------------------------------

1.1	CN570	Addition of coding comb.
-----	-------	--------------------------

S1000 Digital Input Matrix Module – J/G1421

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
-----------------	---------------	------------------------------

1.3	CN614	Degrease before labels attached, improve component spacing.
-----	-------	---