

S500 PSU PCB – G1915

| <u>Revision</u> | <u>Change</u> | <u>Customer Release Note</u> |
|------------------------|----------------------|---|
| 1.05 | CN792 | Rework PCB. |
| 1.04 | CN950 | New supply of transformer introduced for buyer. |
| 1.03 | CN947 | Mechanical change to speed up production. |
| 1.02 | CN921 | Specify alternative diode on parts list for buyer. |
| 1.01 | CN884 | Include additional descriptive info in parts list (manufacturing information). |
| 1.00 | CN844 | Rework pcb to assist production. NB new version will only support lead acid batteries. |
| 0.05 | CN827 | Correct typo in manufacturing info (parts list). |
| 0.04 | CN806 | Revise LPC to support PSTN modem. |
| 0.03 | CN772 | Manufacturing info. |
| 0.02 | CN771 | Allow under tolerance on output from transformer. |
| 0.01 | CN769 | Allow under tolerance on current limit to allow limit to be set more accurately on battery charger. |