

## EA S250 Upgrade Kit – J8202

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.01	CN1301	The fixing of the cables was incorrectly shown using all 6mm P Clips in the manufacturing information. It should be a mixture of 6mm and 9mm.
1.00	-----	Product released to production.