

S500/S250 SEEP Configuration Tool – S1911

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.06	CN1446	Feature #64: Need to support Exec 5.32 new TSP features Feature #66: Remove I23 handler support. Bug #65: Radio bits are not handled correctly for all protocol types Bug #122: CRC type is not setup by Modem Presets Bug #474: Various protocol timeout delay parameters cannot be set < 1.00 correctly
1.05	CN1220	Fix support for Seprol Internal GSM modem. Setup string too long and wrong string for ISDN mode.
1.04	CN1216	Support for internal GSM modem added, Improvements made to Hayses handler.
1.03	CN1209	Add Modem Presets. Timeouts now configured in seconds. Exec 5.19 additions – RLSD, CTS.
1.02	CN1184	Fix copying 19k2 baud between ports. Add configuration of X8000 error suppression. Add configuration of fast start. Add standard installation package via setup.exe.
1.01	CN1096	Comms page certain settings were missed when toggling between pages. Copy comms didn't copy the modem setup string. No support for I/23, TSP or 19K2 baud rate.
1.00	-----	First Release