

S500 Digital Output Card – G1905

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.02	CN1158	I/O were not previous included as an item on the production information.
1.01	CN948	Improved isolation and new relay type.
1.00	CN856	All relays switchable simultaneously. Revised test procedure to aid production.
0.01	CN822	Use PALS pre-programmed by supplier to assist production.