

## **S500 6 SLOT PSU – G1917**

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.01	CN1236	Change spade connectors on mains to 2 pole connector. Also swap R23 and R11.
1.00	-----	Released to production.