

S500 Multifunction Analogue Input – G1918

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.02	CN1385	Rework PCB to add a buffer to serial data line. This allows correct operation with a larger number of cards.
1.01	CN1239	The PCB was reworked to alter the footprint of two components which were proving difficult to solder.
1.00	-----	Released to production.