

S500 Single RS232 – G1922

<u>Revision</u>	<u>Change</u>	<u>Customer Release Note</u>
1.14	CN1475	Use new LED holder.
1.13	CN1388	Errors in manufacturing Information.
1.12	CN1377	Manufacturing information now in PDF format.
1.11	CN1253	IC change to utilize common parts in production - 74HC14 to 74AHC14 and crystal change to low profile variant.
1.10	CN1213	In certain circumstances the RS485 unit would not work on multidrop systems. Modification to control logic to prevent this occurrence.
1.09	CN1206	PCB reworked to incorporate modifications
1.08	CN978	Mechanical change to assist production.
1.07	CN918	Improved test procedure for production.
1.06	CN887	Improved test procedure for production.
1.05	CN857	Improve wake line facility.
1.04	CN834	Add new option and improve manufacturing documentation.
1.03	CN815	Alternative cap packaging style specified.
1.02	CN805	Specify alternative PSU diode.
1.01	CN765	Correct parts list discrepancy.
1.00	-----	Released to production.