

## **S500 Bulldog Modem Interface – G1923**

<b><u>Revision</u></b>	<b><u>Change</u></b>	<b><u>Customer Release Note</u></b>
1.07	CN1378	Manufacturing information now in PDF format.
1.06	CN1245	Connector change from screw down type to clip in type.
1.05	CN1158	Modem cover was not previous included as an item on the production information.
1.04	CN1050	Revise R10 value to improve AA efficiency of bulldog on certain exchanges.
1.03	CN1026	Parts list changed (regulator) and the manufacturing information streamlined.
1.02	CN881	SM connector replaced by through hole type for added mechanical robustness and supply.
1.01	CN813	Alternative CAP packaging style specified. Parts list changed.
1.00	-----	Released to production.